

**A K A I *professional***  
**= SOFTWARE RELEASE =**

Subject: MPC4000 V1.45 Software Release-

The MPC4000 V1.45 has been released with the following additional support and bug fixes from V1.40.

[Additional support]

1. Roland and EmuIV CD-ROMs are now supported.

Loading operation is same as loading from AKAI native CD-ROM.

Each file will be converted to the following files.

Roland

Patch file(.PER)	> Multi program (.akm)
Partial file(.ROP)	> Program (.akp)
Roland sample(.ROS)	> Wav sample

EmuIV

Preset file(.E4P)	> Program (.akp)
E3 sample(.E3S)	> Wav sample

[Bug fixes]

1. If a folder name contains “.” character, the other folders didn’t appear in the Load mode. --- fixed
2. In the Save mode, when performing Save Multi/Save Program with “Replace same files/samples: Yes”, Multi/Program wouldn’t always overwrite correctly. --- fixed
3. In the Load/Save mode, Disk Free field was not displayed correctly after formatting particular hard drive. --- fixed
4. In the Load/Save mode, when trying to rename an un-formatted hard drive, Fatal error would happen. --- fixed
5. In the Load mode with CD-ROM, rarely File List was not displayed correctly. --- fixed
6. In the Load/Save mode, when closing ”File Information/Folder Information” pop up window, cursor was moved to the top of the file list automatically. --- fixed
7. In the Main mode etc., GO TO key and “EVENT<” key were not functioning properly. --- fixed
8. Panic function by triple pressing Stop key was not working sometimes except in the Sample mode. --- fixed
9. In the Track Mute > Edit page, when performing Insert/Delete on a Mute Event, other Sequence data would be deleted. --- fixed
10. In the Seq. Edit mode, Copy & Paste didn’t function correctly. --- fixed

- end of file -